

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- Firmware Version:
T48G: 35.72.0.225 Upgrade to 35.73.0.50
T46G: 28.71.0.224 Upgrade to 28.73.0.50
T42G: 29.71.0.224 Upgrade to 29.73.0.50
T41P: 36.71.0.224 Upgrade to 36.73.0.50
Applicable Models: SIP-T48G/T46G/T42G/T41P
- Release Date: Feb 5th, 2015.

2. New Features

3. Optimization

4. Bug Fixes

1. Fixed the issue that when the key of Action URI was set as auto Provision during calling, the LCD screen would displayed “Talking” after ending the call.
2. Fixed the issue that the BLF would causing an exception in the T46G when the attended transfer mode was set via Dsskey.
3. Fixed the issue that the LCD screen would become blank space after rebooting, when the RPS of T41 and T42 were both configured to be enabled.
4. Fixed the error searching for the keyword search of “äöü” in the local phonebook and remote phonebook when the language of the phone was German.
5. Modified the LCD display name “ktiv” to “Aktiv” in the Status user interface, when the language of the phone was German.

- 5. New Features Descriptions**
- 6. Optimization Descriptions**
- 7. Configuration Parameters Enhancements**

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- Firmware Version:
 - T46G: 28.71.0.176 Upgrade to 28.71.0.224
 - T42G: 29.71.0.53 Upgrade to 29.71.0.224
 - T41P: 36.71.0.112 Upgrade to 36.71.0.224
 - Applicable Models: SIP-T46G/T42G/T41P
- Release Date: June 19, 2014

2. New Features

3. Optimization

4. Bug Fixes

1. Fixed the issue that the T4 series displayed a wrong call ID when using directed call pickup of a monitored BLF line.
2. Fixed the issue that the BLF doesn't work under 3CX SBC environment.

5. New Features Descriptions

6. Optimization Descriptions

7. Configuration Parameters Enhancements