

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- Firmware Version:
 - T28P: 2.71.1.1 Upgrade to 2.73.0.50
 - T26P: 6.71.1.1 Upgrade to 6.73.0.50
 - T22P: 7.71.1.1 Upgrade to 7.73.0.50
 - T20P: 9.71.1.1 Upgrade to 9.73.0.50
- Applicable Models: SIP-T28P/T26P/T22P/T20P
- Release Date: Feb 5th, 2015.

2. New Features

3. Optimization

4. Bug Fixes

1. Fixed the issue that when the key of Action URI was set as auto Provision during calling, the LCD screen would displayed “Talking” after ending the call.
2. Fixed the issue that the BLF would causing an exception in the T46G when the attended transfer mode was set via Dsskey.
3. Fixed the issue that the LCD screen would become blank space after rebooting, when the RPS of T41 and T42 were both configured to be enabled.
4. Fixed the error searching for the keyword search of “äöü” in the local phonebook and remote phonebook when the language of the phone was German.
5. Modified the LCD display name “ktiv” to “Aktiv” in the Status user interface, when the language of the phone was German.

- 5. New Features Descriptions**
- 6. Optimization Descriptions**
- 7. Configuration Parameters Enhancements**

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- **Firmware Version:**

T28P: 2.71.0.224 Upgrade to 2.71.1.1

T26P: 6.71.0.224 Upgrade to 6.71.1.1

T22P: 7.71.0.224 Upgrade to 7.71.1.1

T20P: 9.71.0.224 Upgrade to 9.71.1.1

- **Applicable Models:** SIP-T28P/T26P/T22P/T20P

- **Release Date:** Oct 29th, 2014.

2. New features

No new features added on the new commercial version.

3. Bug fixes

1. Fixed the issue that the “Action URI: key = HOLD” could not be taken effect when using the CTI feature.

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

- **Firmware Version:**

T28P: 2.71.0.168 Upgrade to 2.71.0.224

T26P: 6.71.0.168 Upgrade to 6.71.0.224

T22P: 7.71.0.168 Upgrade to 7.71.0.224

T20P: 9.71.0.168 Upgrade to 9.71.0.224

- **Applicable Models:** SIP-T28P/T26P/T22P/T20P

- **Release Date:** June 19th, 2014.

2. New features

1. Added the language support of Russian to the T2x series SIP phone.

3. Optimization

4. Bug Fixes

1. Fixed the issue that the Hot Desking feature could not work normally.
2. Fixed the issue that the BLF doesn't work under 3CX SBC environment.