



March 16, 2017

Greetings,

BroadSoft is pleased to announce that the Yealink T5xx series has been formally validated with BroadWorks. The device model(s) listed below have been validated as interoperable with the BroadWorks SIP interface. Configuration details and any issues or limitations identified during the interoperability testing are documented in the BroadSoft Partner Configuration Guide (PCG) *PartnerConfigGuide Yealink T5XX Series*>. The PCG is available to BroadSoft customers on the BroadSoft Xchange website at [xchange.broadsoft.com](http://xchange.broadsoft.com).

BroadSoft validates that the device interoperates with the BroadWorks SIP interface. BroadSoft does not validate qualitative aspects of the device, capacity, or other device capabilities outside the scope of the SIP signaling interface.

The validation covers the Yealink version(s) and BroadWorks release listed below. Other versions tested previously are documented in the PCG.

Yealink T56A, T58A, T58V version 58.80.193.5 \*  
BroadWorks Release 22.0

\*This validation also applies to all subsequent compatible maintenance releases to this device version.

Best Regards,

A handwritten signature in black ink that reads 'Wesley Hacker'.

Wesley Hacker  
Director, Solutions Engineering  
+1.240.364.5149  
[wesley@broadsoft.com](mailto:wesley@broadsoft.com)